


# UPRI PIPELINE REPAIR REPORT

## HATTON AREA

Date of Repair: Nov. 1/00 14-17-15-26w3 20001101

Location of Repair: 14 Qrter of Sec. 17 Twp 15 Rge 28 West 3 Meridian

Diagram showing (1-pipeline as runs through sec....2-repair relative to well/s or landmarks...3-off right of way access..)



Landowner: Gerald Ebel

Landlessor: Terry Herker

Landuse: cultivation  pasture

Off right of way access distance to site: 325 ~~100~~ ft

Length of excavation of end to end including bell holes: 19 Meters

Size of pipe affected: 8 Inch

Suspected cause of failure: - internal Corrossion

Description of repair: - cut out and inspected; then replaced 42 feet of new 8" line pipe. Back filled excavation and laid topsoil back on site.

Operator signature: [Signature]  
Operator contact # 3066694617

FAX TO DISTRICT OFFICE # 669-2160 (Phone 306-669-6600)  
FAX TO U.P.R.I. LAND DEPARTMENT # 1-403-231-0174  
FAX TO S.E.M. SWIFT CURRENT # 1-306-778-8256.....Attention: Ron Dolter